TECH I

FAT-MAT INSTRUCTIONS

The tape-less, clamp-less and vacuum-less way to hold your work piece! Our Fat-Mat will secure materials such as plastic, brass, acrylic, marble, aluminum, and more for fast and effective engraving and lasering applications. Fat-Mat eliminates sticky residue on engraving materials.



Fat-Mat Instructions:

- 1. Clean your engraving table of dust, oils, engraving chips, etc.
- 2. Adjust your spindle travel to allow for depth of mat.
- 3. Optional: Lay a strip of low tack Doublesurfaced tape on your table. Place Fat-Mat, acrylic side down, on tape or table.
- 4. Place engraving material on top of Fat-Mat and begin engraving.
- 5. Remove engraving material from mat and repeat process.
- 6. Clean Fat-Mat regularly with rubbing alcohol and a lint-free cloth. This helps keep your mat in its original form and engraving to the accurate depth.
- 7. Fat-Mat has a 9 to 12 month life expectancy with proper care and daily cleaning.









