TECH I

ΕΔΤ-ΜΔΤ

The tape-less, clamp-less and vacuum-less way to hold your work piece! Our Fat-Mat will secure materials such as plastic, brass, acrylic, marble, aluminum, and more for fast and effective engraving and lasering applications. Fat-Mat eliminates sticky residue on engraving materials.

Fat-Mat Sizes Available: Item# FMAT01	Sizes 5"x 7" 13x18cm
FMAT02	8"x 12" 20x30cm
FMAT03	9"x 12" 23x30cm
FMAT04	12"x 12" 30x30cm
FMAT05	13"x 13" 33x33cm
FMAT06	12"x 16" 30x41cm
FMAT07	12"x 24" 30x60cm

Custom Sizes Available Upon Request





Fat-Mat Instructions:

- 1. Clean your engraving table of dust, oils, engraving chips, etc.
- 2. Adjust your spindle travel to allow for depth of mat.
- 3. Optional: Lay a strip of low tack doublesurfaced tape on your table. Place Fat-Mat, acrylic side down, on tape or table.
- 4. Place engraving material on top of Fat-Mat and begin engraving.
- 5. Remove engraving material from mat and repeat process.
- 6. Clean Fat-Mat regularly with rubbing alcohol and a lint-free cloth. This helps keep your mat in its original form and engraving to the accurate depth.
- 7. Fat-Mat has a 9 to 12 month life expectancy with proper care and daily cleaning.







