

## SUBLIMATABLE GARDEN FLAG


GF3045, GF4768

### Settings

- **Time:** 60 seconds
- **Temperature:** 356° F
- **Pressure:** Moderate

### Tools

- Vapor Foam Kit or heat foam



### Fabrication Process

- Place piece of foam on press bed to ensure even pressure.
- Place sacrificial paper over the foam.
- Position transfer to the top of the flag. (secure w/ heat tape if needed)
- Set item on prepared bed.
- Place additional sheet of sacrificial paper over the flag.
- Press the flag.

### Note:

Both sides of flag can be sublimated however the images can often be seen through the other side.