

## Sublimatable Garden Flag - 11X18 - GFDS001

## **Settings**

• Time: 120 - 150 seconds • Temperature: 350 - 360° F • Pressure: Moderate to Heavy

## **Sublimation Process**

- Preheat the heat press to 350-360F.
- Place the blank flag onto the printed transfer paper. Secure with heat tape.
- Place blowout paper onto the bottom platen of the heat press.

**Tip**: When setting up your artwork, utilize the product template found on the product page for this item on JPPlus.com.

- Place the flag with attached transfer paper onto the heat press with the transfer paper on top.
- Place an additional piece of blowout paper on top of the transfer paper.
- Close and press for recommended time.
- When finished, open the heat press and remove the flag. Remove the transfer paper from the flag and discard.
- If pressing the second side of the flag, it is recommended to replace the blowout paper on the bottom of the heat press with a new sheet.
- To press the second side of the flag, repeat the steps 5-8.

Note: Due to variances in conditions and equipment, minor setting adjustments may be needed to achieve optimal results.

