

## Crystal Awards

Part # CA1\_\_ series

### Sublimation Instructions

**PREHEAT** your press to 425° F

**PRINT THE TRANSFER** – DO NOT mirror your image

**USE GREEN SPONGE HEAT PAD** – Place printed sublimation paper on top of crystal award (printed side towards white coated side of glass), and secure with heat tape. Place Green Sponge Pad on top of sublimation paper. We recommend the Geo Knight brand.

**PRESSURE** – Use a setting of 3-5 if your press has been calibrated, or medium light pressure


**TEMPERATURE** – 425° F

**TIME** – 9-10 minutes

**FOR BEST RESULTS:**

Leave secured paper attached and lay the glass flat on an even surface to cool

Place your items on the heat press in this order



rev. 1 Nov. 2016

**Adhering Award to Base** – If desired, adhere award to included base. We recommend Loctite Glass Glue, Gorilla Glue Super Glue, or UV-Curable Glass Adhesive.