

PU LEATHER PRODUCTS

LMC1, LMC2, LKC7, LKC8

Settings

- **Time:** 50 seconds
- **Temperature:** 385° F
- **Pressure:** Extremely Light (*press should just be laying on top of leather product applying no pressure*)



Fabrication Process

- Place silicone finishing sheet on press bed. (*Silicone sheets Item # 17-SILICONE50*)
- Place transfer onto the white sublimatable surface. Secure with heat tape on the outside edge of the product.
- Set the product w/transfer on top of silicone paper on press bed.
- Place another sheet of silicone paper over the transfer.
- Lightly press product. (*see note above*)
- After 50 seconds, lift press, remove silicon paper and leather product.

Notes:

- Size artwork to have 1/8" bleed on all edges.
- To prevent an impression from tape, only apply tape to the very edge of the product, outside of the stitching.